DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-013419 Address: 333 Burma Road **Date Inspected:** 04-Feb-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li yuan hua No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** component

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, S.Chandrakumar was present during the times noted above for observations relative to the work being performed.

Outside Yard: Segment 8CE.

This QA inspector observed ZPMC qualified welding personnel identified as 043661 and 058087 perform Shielded Metal Arc Welding (SMAW) Welding on T-ribs edge plate misalignment weld joints of segment 8CE cross beam side. The weld joint details are identified as PP69.5-PP70-13, 14, 15, 16, 17, 18, 19(T-ribs numbers); PP69-PP69.5- 17, 18; PP68-PP68.5- 19. ZPMC QC is identified as Mr. Zhang Zin. The approved Welding Repair Report (WRR) is identified as B-CWR10632. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-345-SMAW-3G (3F) Repair.

This QA inspector observed ZPMC qualified welding personnel performing weld repair / correction on Flange Plate X7K of PP68, PP69, PP70 and PP71 to maintain the required radius R50mm. The welding process is identified as Shielded Metal Arc Welding (SMAW) and the welder is identified as 043661. ZPMC QC is identified as Zhang Zin. The welding variables recorded by QC appeared to comply with the applicable WPS: 345-SMAW-1G (1F)-Repair, which is used as per Welding Repair Report (WRR) B-WR10642.

BAY#14

This QA Inspector observed ZPMC personnel performing Heat straightening on traveler Rail at bay#14.The Traveler rail is identified as 11TR1-002.

This QA Inspector observed ABF personnel performing Ultrasonic Testing (UT) on the Edge Plate to Deck Plate corner CJP weld at Segment 9BW cross beam side.

BLAST SHOP 1

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Caltrans Quality Assurance (QA) Inspectors performed random visual inspection of OBG segment 8CE external side panel, bottom panel, Deck panel floor beam and longitudinal diaphragms surfaces from the panel point 68 to 70 after grit blasting. Areas that marked for repair were recorded for future repair. Areas requiring additional grinding were marked by QA and repaired by ZPMC personnel.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang-15--0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Chadra	Quality Assurance Inspector
Reviewed By:	McClendon, Timothy	QA Reviewer